


INSTRUCTIONS

GEI-28838D


INSTALLATION OF PRIMARY CABLES IN METAL-ENCLOSED SWITCHGEAR



MEDIUM VOLTAGE SWITCHGEAR DEPARTMENT


GENERAL  ELECTRIC

PHILADELPHIA, PA.



USE 4 GALS. GE[®] ZET CONE TO FILL POTHEAD AFTER MAKING CABLE CONNECTIONS
 FINISH WITH 10 MILS. VC TAPE 4 LAYERS 1/2 LAP PAINT WITH GE. 462 BURNISH
 TAPPED UP WITH 10 MILS. VC TAPE CENTER OF BUILD UP TO HAVE 75% MORE TAPE THAN ORIGINAL INSULATION
 1/2" COPPER BRAID TO BE CUT AT AN ANGLE OF 15° & SOLDERED TO COPPER SHIELD TAPE ON CABLE. BRAID TO BE WOUND TIGHT AND CLOSE. ALL TURNS OF BRAID TO BE SOLDERED ALONG TWO LINES PARALLEL TO CABLE TO PREVENT SEPARATION
 COPPER BRAID TO BE WOUND AROUND METALLIC BANDER AND SOLDERED BOTH TO BANDER AND LEAD SHEATH.

FOR BELTED CABLE
 APPLY 1/2" TAPE IN FIRMLY DRAWN WRAPPINGS ON EACH CONDUCTOR IN THE REGION OF THE CABLE CRITCH AS INDICATED ON THE DRAWING. THE AXIAL DIMENSIONS FOR THE REINFORCEMENT ARE INDICATED. THE MAXIMUM THICKNESS OF THE APPLIED TAPE SHOULD BE EQUAL APPROXIMATELY THAT OF THE ORIGINAL CONDUCTOR INSULATION. AFTER COMPLETION OF THE INDIVIDUAL REINFORCEMENTS, APPLY 1" WRAPPINGS TAPE OVER THE THREE CONDUCTORS FORCED TOGETHER IN THE CRITCH REGION.
 SOLDER A PORTION OF THE OVER-ALL REINFORCEMENT AS INDICATED. TRIM ONE END OF THE COPPER BRAID TO AN ANGLE APPROXIMATELY 15 DEGS. AND LAY IT ON THE SHEATH BAND WITH THE CUT EDGE TOWARD THE SHEATH. SOLDER IT TO THE SHEATH. THEN COVER THE SHEATH BAND, EXPOSED BELT INSULATION AND THE ADJACENTLY TAPERED SURFACE OF BEBEL REINFORCEMENT WITH A SINGLE LAYER OF TIGHTLY DRAWN BUTT WRAPPINGS OF BRAID AS SHOWN. SOLDER TOGETHER ALL TURNS ON OPPOSITE SIDES OF THE BAND, AND TERMINATE THE BRAID BY CUTTING 1/2" BEYOND A SOLDERED POINT. THE LOOSE END OF THE BRAID SHOULD BE TURNED BACK AND SOLDERED TO THE PRECEDING TURNS SO THAT NO FRayed ENDS OF COPPER EXTEND OVER THE WRAPPED CLOTH.



NOTE
 PHASE POSITION TO BE CHECKED BEFORE CONNECTING TO POTHEAD TERMINALS

Fig. 1 G.E. Triple-Conductor Pothead Assembly

Fig. 1 (T-6595322)

Fig. 19 (K-660614)

Cover (8006225)

Fig. 20 (414A757)

INSTALLATION OF PRIMARY CABLES IN METAL-ENCLOSED SWITCHGEAR

INTRODUCTION

Before any primary cable connections are made, the cables should be identified to indicate their phase relationship with the switchgear connections. This is necessary to insure that the connections are made so that motors will rotate in the proper direction, and the phase rotation is the same when tying two different sources of power together.

There are two common methods of making primary cable connections:

(a) Potheads, Figs. 1 and 20 are used when it is desired to hermetically seal the end of the cable to make a moisture proof connection between the cable and the switchgear copper. A pothead also prevents seeping of oil from the end of oil impreg-

nated varnished cambric or paper insulated cable.

(b) Clamp type terminals and wiping sleeve or cable clamp.

In all cases carefully follow the cable manufacturer's recommendations for installation of the type of cable being used, as well as the instructions contained herein.

INSTALLATION

The following description applies to the installation of a three-conductor lead-sheathed cable with a wiping sleeve cable entrance fitting on the pothead. This is the type most generally used. Instructions for installation of other types are included in the text following:

(a) Remove the wiping sleeve and cut the tapered end at a point where the cable will enter it freely, and file off sharp edges. Temporarily reassemble on the pothead.

(b) Train the cable in front of the

pothead allowing it to extend about two inches above the top of the porcelain bushings. Handle with care and avoid sharp bending which might damage the insulation. Mark a point on the lead sheath of the cable about 1-1/2 inch above the bottom of the wiping sleeve.

Fig. 2 (8001619)

Fig. 3 (8008094)



Fig. 2 G-E Potheads Mounted




Fig. 3 G-E Potheads Mounted

These instructions do not purport to cover all details or variations in equipment nor to provide for every possible contingency to be met in connection with installation, operation or maintenance. Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes, the matter should be referred to the General Electric Company.

(c) Remove the pothead from the unit, disassemble the wiping sleeve and slip it and its gasket over the cable as shown in Fig. 4.




Fig. 4

(d) Remove the lead sheath from the cable to the point marked in operation "b" as shown in Figs. 5 and 6 proceeding as follows:




Fig. 5

First, make a cut around the cable half through the sheath at the reference point. Second, split the sheath lengthwise between the cut and the cable, holding the cutting tool at an angle to the cable radius to avoid damaging the insulation. Third, remove the sheath by catching the split edge with pliers and pulling directly away from the cable axis.

Clean and tin the outside of the lead sheath for about 3 inches and bell out the end of the lead sheath.

(e) Remove the belt and interphase insulation down to within 1-1/2 inches of the lead sheath as shown in Fig. 7. The last few layers should be torn off to avoid damaging the individual conductor insulation. To reinforce and protect the conductor insulation, wrap two layers of half lapped varnished cambric tape over the factory insulation.




Fig. 6



Fig. 7

(f) Disassemble insulator support plate from pothead body. The insulator should not be removed from the support plate because they are factory assembled for proper compression of their gaskets. Place pothead body over cable and then fan out the conductors into approximately the final position, as shown in Figs. 8 and 9. The middle conductor should be bowed slightly for final adjustment of length. Avoid sharp bends and damage to the insulation, particularly at the crotch.



Fig. 8



Fig. 9

(g) For system voltage above 7500 volts it is recommended that stress relief cones be built up when single-conductor or three-conductor shielded cable is used. Construct stress relief cones in accordance with the recommendations of the cable manufacturer. See Fig. 1 for one recommended method. On lower voltage cables, belling out the end of the lead sheath ordinarily provides sufficient stress relief. (Stress cone material will not be furnished with pothead).

(h) Bolt pothead body to metal-clad adapter plate. Shape conductors into final position, then cut off each conductor to fit its terminal.

(i) Remove pothead terminals from insulators. Remove two inches of insulation from the end of each conductor and assemble pothead terminals to cables.



Fig. 10




Fig. 11

(j) Assemble gaskets where shown in Fig. 1 and bolt insulator support plate and wiping sleeve to pothead body. Compress gaskets by a partial turn on each bolt successively until the gasket is uniformly compressed to dimensions shown in Fig. 1. Check to be sure the terminal studs are seated properly on their gaskets, then screw contact nut in place after assembling top gaskets and washers. See Figs. 9, 10 and 11.

Fig. 4 (857623)
Fig. 5 (857622)

Fig. 6 (857621)
Fig. 7 (857618)

Fig. 8 (857611)
Fig. 9 (857606)

Fig. 10 (857619)
Fig. 11 (857610)

(k) Make a plumber's wiped joint between the wiping sleeve and the lead sheath of the cable, as shown in Figs. 12 and 13.

(l) Remove the 3/4" filling plug in the pothead body, the pipe plugs in the top of the studs and in the insulator support plate. Insert a stand pipe and funnel in the filling hole of sufficient height to extend above the top of the studs as shown in Fig. 14.

Heat #227 compound to the pouring temperature, 165 C. Do not overheat compound as higher temperatures may injure cable insulation and also result in excessive shrinkage of the compound while cooling. Before and while filling, warm pothead body and stand pipe to prevent sudden chilling of compound which may result in the formation of air voids. The pothead may be warmed by playing a blowtorch over the body, taking care that no direct heat reaches the porcelains or gaskets.

Pour until the compound appears at the insulator support plate plug holes. Insert plugs and continue filling until it appears at holes at the top of terminal studs. Insert plugs and continue pouring while the pothead and compound cools to fill air voids which might form.

When the pothead has cooled, remove filling pipe and insert plug. Clean off compound which might have overflowed on the outside of the porcelains.

(m) Assemble pothead connection bars (see Fig. 15), and insulate connections as follows:

(1) Fill all cavities around bolts and nuts with Duxseal compound to form smooth surface for taping, thus preventing air voids. This compound is not an insulating medium and should not be used for that purpose.

(2) Wrap with insulating tape provided, as shown in Fig. 19, the number of layers depending on the voltage rating of the equipment and the type of tape used. Where there are sharp angles, apply additional layers to obtain the equivalent of the insulation of the flat surfaces.

(3) Over the insulating tape, apply one layer of white cotton tape, half lap, as a binder.

(4) Over the white cotton tape, brush a good coat of G. E. Glyptal* varnish (#1201 Red for 15 KV and #462 Black for 5 KV).

Single-Conductor Potheads

The procedure for installation of single-conductor potheads is in general the same as described for three-conductor potheads. Refer to Fig. 20.

* Reg. Trade-Mark of General Electric Co.



Fig. 12



Fig. 13



Fig. 14



Fig. 15

Cable Entrances Other Than Wiping Sleeve

Stuffing box cable entrance fittings, Fig. 16, are used for nonlead-covered cable, and are installed as follows: Assemble stuffing box in pothead. Wrap graphite cord packing around the cable and compress by screwing the gland nut into the stuffing box.

A combination clamping ring and stuffing box is sometimes furnished instead of a wiping sleeve for lead-covered cables. This fitting is installed as follows: Wrap graphite cord packing around cable and compress by screwing gland nut into stuffing box. Bell over lead sheath and notch the edges to expose screw holes. (Note the openings in the fitting below the notches,

which permit compound to reach the sheath and seal any splits which might occur while belling over and notching).

Clamp lead sheath with ring and trim off sheath smoothly. Leave about 1-1/2 inch of belt insulation above the clamping ring.

Cable Sheath Grounding

Where three-conductor, lead-sheathed cables are installed, it is advisable to ground the sheath directly to the ground bus in the switchgear. Where single-conductor lead-sheathed cables are used, the same procedure may be followed except that only one end of the cable sheath should be grounded.




Fig. 16 Stuffing Box (with or without Clamping Ring)




Fig. 17 Termination Non-Leaded Cable Single Conductor

Rated kv Phase to Phase	Dimensions in Inches	
	A	B
2 to 5	5	2
6 to 10	9	3
11 to 15	13	4

TERMINATION NONLEADED CABLE SINGLE-CONDUCTOR

1. Cut cable to proper length.
2. Remove jacket and cable tape for distance of A plus B plus 3 inches, plus length to be inserted into terminal lug.
3. Unwrap shielding tape to point M, cut and solder it in place avoiding excessive heat on insulation. Remove outer semi-conducting tape for same distance. Thoroughly clean surface from which the semi-conducting tape was removed.
4. Remove insulation and inner semi-conducting tape to expose conductor for distance of one inch plus length to be inserted into terminal lug.
5. Attach terminal lug to conductor.
6. Taper insulation for one inch as shown.
7. Apply end seal. Clean surface over which splicing tape is to be applied and coat with G.E. No. A50P68 adhesive cement or equivalent. When solvent evaporates, build up with splicing tape GE8380 or equivalent, as shown.
8. Build stress cone. Clean cable surface and coat with G.E. No. A50P68 adhesive cement or equivalent. When solvent evaporates, build up cone with splicing tape GE8380 or equivalent, for length B plus B. Between points M and P, tape is applied so that wrapped thickness at N is equal to 75% of the original insulation thickness - and so that the cone tapers to zero thickness at points M and P. Apply one layer No. 33 Scotch tape or equivalent, half lapped. Obtain a smooth wrapping but do not stretch tape more than necessary.

9. Pass a turn of tightly drawn braid around exposed portion of shielding tape at point M and solder in place. Then apply shielding braid in tightly drawn 1/16 inch lap wrappings to point N and spot solder. Terminate the braid by cutting 1/2 inch beyond soldering point. Turn down and solder loose ends to preceding turns. Wrap four to six turns of No. 19 AWG tinned copper wire around shielding braid and solder. Solder all turns of braid together along three lengthwise lines equally spaced around braided surface.

10. Solder-attach ground strip over shielding tape near cable covering. Cover stress cone with one layer No. 33 Scotch tape, half lapped. Obtain a smooth wrapping but do not stretch tape more than necessary. Add two layers of splicing tape.

11. Pencil jacket for 1/2 inch as shown. Clean surface. The particular care in cleaning outside jacket surface in order to entirely remove black wax finish. Coat with G.E. No. A50P68 adhesive cement or equivalent. When solvent evaporates, apply splicing tape GE8380 or equivalent and make sheath seal as shown on drawing. Apply one layer No. 33 Scotch tape or equivalent, half lapped. Obtain a smooth wrapping but do not stretch tape more than necessary.

12. Over entire termination, apply two layers of No. 33 Scotch tape or equivalent, half lapped, in manner to shed water. Obtain a smooth wrapping but do not stretch tape more than necessary.





Fig. 18 Termination Non-Leaded Cable Multi Conductor

TERMINATION NONLEADED CABLE MULTI-CONDUCTOR

Make termination as indicated for single-conductor except - substitute the following for paragraphs 10, 11 and 12.

Pencil Geoprene jacket 1/2 inch. Clean surface over which sheath moisture seal is to be applied. Take particular care in cleaning outside jacket surface in order to entirely remove black wax finish. Coat with G.E. No. A50P68 adhesive cement or equivalent. Allow to dry. Apply splicing tape GE8380 or equivalent to make moisture seal as shown. This is done by starting wrapping tape near end of jacket and wrapping over ground wires for 1-1/2 inches. Bend ground wires out and back over taping just applied and continue applying lapped layers of tape to completion of moisture seal including a complete tape seal in crotch formed between the three conductors. Bond and ground the ground wires.

For a multi-conductor cable not having ground wires, the individual terminations should have grounding strips applied as for a single-conductor termination. These grounding strips are to be joined together to a common ground. This common ground must then be grounded.



INSULATION LEVEL	INSULATION LAYERS		
	V.C.	COTTON TAPE	I-202
5000 V.	4	1	2
15000 V.	7	1	4

NOTE FOR VARNISHED CAMBRIC

V.C. IS BLACK VARNISHED CLOTH (CAMBRIC) TAPE #992 WIDTH 1 1/2" THICKNESS .012 COTTON TAPE IS WHITE G.E. A12A1D10 WIDTH 1 1/2" *ONE LAYER (WOUND 2/3 LAP) REQUIRES 3 TURNS AROUND BAR IN ONE WIDTH OF TAPE. THE THICKNESS OF ONE LAYER IS 3 TIMES THE THICKNESS OF THE TAPE.

NOTE FOR IPRATHENE

I-202 BLACK IPRATHENE TAPE WIDTH 1 1/2" THICKNESS .010 COTTON TAPE IS WHITE G.E. A12A1D10 WIDTH 1 1/2"

Fig. 19 Insulation of Connection Bars




Fig. 20 Single-Conductor Pothead Assembly

WHEN YOU NEED SERVICE

IF YOU NEED TO REPAIR, recondition, or rebuild any electric apparatus, a G-E service shop near you is available day and night, seven days a week, for work in the shops or on your premises. Latest factory methods and genuine G-E renewal parts are used to maintain the original performance of your G-E equipment. For full information about these services, contact the nearest service shop or sales office listed below:

APPARATUS SERVICE SHOPS

Allentown, Pa. 672-676 E. Highland St.
 Appleton, Wisc. Midway Industrial Area,
 County Trunk, "P"
 Atlanta—Chamblee, Ga. 4639 Peachtree
 Indus. Blvd.
 Baltimore 30, Md. 920 E. Fort Ave.
 Boston—Medford 55, Mass. Mystic Valley Pkwy.
 Buffalo 11, N. Y. 318 Urban St.
 Charleston 28, W. Va. 306 MacCorkle Ave., S.E.
 Charlotte, N. C. 2328 Thrift Road
 Chicago 32, Ill. 4360 W. 47th St.
 Cincinnati 2, Ohio. 444 W. Third St.
 Cleveland 4, Ohio. 4966 Woodland Ave.
 Columbus 23, Ohio. 2128 Eakin Rd.
 Corpus Christi, Texas. 115 Busse St.
 Dallas 19, Texas. 3202 Manor Way
 Davenport—Bettendorf, Ia. 1039 State St.
 Decatur, Ill. 2225 E. Logan St.
 Denver 5, Colo. 3353 Larimer St.
 Detroit 2, Mich. 5950 Third Ave.
 Houston 20, Texas. 5534 Harvey Wilson Drive
 Indianapolis 22, Ind. 1740 W. Vermont St.
 Johnstown, Pa. 841 Oak St.
 Kansas City, Mo. 3525 Gardner Ave.
 Los Angeles 1, Calif. 6900 Stanford Ave.
 Louisville, Ky. 2014 New Main St.
 Midland, Tex. 3404 Bankhead Hwy.
 Milwaukee 3, Wisc. 940 W. St. Paul Ave.
 Minneapolis 12, Minn. 2025 49th Ave., N.
 New Orleans, La. 2815 N. Robertson St.
 New York—N. Bergen, N. J. 6001 Tonnelle Ave.
 Oakland, Calif. 1525 Peralta St.
 Philadelphia 24, Pa. 1040 E. Erie Ave.
 Pittsburgh 6, Pa. 6519 Penn Ave.
 Portland 10, Oregon. 2727 N.W. 29th Ave.
 Richmond 24, Va. 1403 Ingram Ave.
 Roanoke, Va. 115 Albermarle St.
 Sacramento, Calif. 99 N. 17th St.
 St. Louis 10, Mo. 1115 East Road
 Salt Lake City 4, Utah. 301 S. Seventh West St.
 San Francisco 3, Calif. 1098 Harrison St.
 Seattle 4, Wash. 3422 First Ave., S.
 Southington, Conn. 53 Railroad Ave.
 Spokane 3, Wash. S. 155 Sherman St.
 Tampa 1, Fla. P.O. Box 1245,
 Naval Indus. Res. Shipyard

Toledo 4, Ohio. 1 So. St. Clair St.
 Wheeling, W. Va. 2050 National Rd.
 York, Pa. 54 N. Harrison St.
 Youngstown 5, Ohio. 272 E. Indianola Ave.

APPARATUS SALES OFFICES

Abilene, Texas. 442 Cedar St.
 Akron 8, Ohio. 335 S. Main St.
 Albany 7, N. Y. 90 State St.
 Albuquerque, N. Mex. 323 Third St., S.W.
 Alexandria, La. 720 Murray St.
 Allentown, Pa. 1132 Hamilton St.
 Amarillo, Texas. Amarillo Bldg.
 Appleton, Wisc. 531 W. College Ave.
 Atlanta 3, Ga. 1860 Peachtree Rd., N.W.
 Augusta, Ga. Masonic Bldg.
 Augusta, Me. 152 State St.
 Baltimore 1, Md. 111 Park Ave.
 Bangor, Maine 77 Central St.
 Baton Rouge 6, La. 3170 Florida Blvd.
 Battle Creek, Mich. 25 W. Michigan Ave.
 Beaumont, Texas. 1385 Calder Ave.
 Billings, Mont. Rm. 816, 303 No. Broadway
 Binghamton, N. Y. 19 Chenango St.

Birmingham 3, Ala. 1804 Seventh Ave., N.
 Bismarck, N. Dak. 418 Rosser Ave.
 Bluefield, W. Va. 704 Bland St.
 Appalachian Bldg.

Boise, Idaho 1524 Idaho St.
 Boston 1, Mass. 140 Federal St.
 Buffalo 3, N. Y. 535 Washington St.
 Butte, Mont. P.O. Box 836, 103 N. Wyoming St.
 Canton 2, Ohio. 700 Tuscarawas St., W.
 Cedar Rapids, Iowa. 210 Second St., S.E.
 Charleston 28, W. Va. 306 MacCorkle Ave., S.E.
 Charlotte 1, N. C. 112 S. Tryon St.
 Chattanooga 2, Tenn. 832 Georgia Ave.
 Chicago 80, Ill. P.O. Box 5970A, 840 S. Conal St.
 Cincinnati 2, Ohio. 215 W. Third St.
 Cleveland 4, Ohio. 4966 Woodland Ave.
 Columbia 1, S.C. P.O. Box 1434, 1420 Lady St.
 Columbus 15, Ohio. 40 S. Third St.
 Corpus Christi, Texas. 205 N. Chaparral
 Dallas 2, Texas. 1801 N. Lamar St.
 Davenport—Bettendorf, Ia. 1039 State St.
 Dayton 2, Ohio. 11 W. Monument Bldg.
 Dayton 9, Ohio. Avia. & Def.,

2600 Far Hills Ave.
 Denver 2, Colo. 650 Seventeenth St.
 Des Moines 9, Iowa. 505 W. Fifth Ave.
 Detroit 2, Mich. 700 Antoinette St.
 Duluth 2, Minn. 14 W. Superior St.
 Elmira, N. Y. Main and Woodlawn Aves.
 El Paso, Texas. 215 No. Stanton
 Erie, Pa. 1001 State St.
 Eugene, Ore. Cascade Bldg., 1170 Pearl St.
 Evansville 19, Ind. 123 N.W. Fourth St.
 Fairmont, W. Va. 370 Jacobs Bldg.,
 P.O. Box 1626

Fergus Falls, Minn. 108 N. Court Ave. P.O. Box 197
 Flint 3, Mich. 653 S. Saginaw St.
 Fort Wayne 6, Ind. 3606 So. Calhoun St.
 Fort Worth 2, Tex. 408 W. Seventh St.
 Fort Worth, Tex. Avia. & Def.,

6200 Camp Bowie Blvd.
 Fresno 1, Calif. 407 Patterson Bldg.
 Tulare and Fulton St
 Grand Rapids 2, Mich. 425 Cherry St., SE
 Greensboro, N. C. 301 S. Elm St.
 Greenville, S. C. 108 W. Washington St.
 Gulfport, Miss. 207 Jo-Fran Bldg.

Hagerstown, Md. Professional Arts Bldg.
 Hartford 5, Conn. 764 Asylum Ave.
 Houston 1, Texas. 1312 Live Oak St.
 Indianapolis 4, Ind. 110 N. Illinois St.
 Jackson, Mich. 120 W. Michigan Ave.
 Jackson 1, Miss. 203 W. Capitol St.
 Jacksonville 2, Fla. 700 E. Union St.
 Jamestown, N. Y. P.O. Box 548, 2 Second St.
 Johnstown, Pa. 841 Oak St.
 Joplin, Mo. P.O. Box 948, 220 1/2 W. Fourth St.
 Kalamazoo 3, Mich. 112 Parkway Ave.
 Kansas City 6, Mo. 106 W. Fourteenth St.
 Knoxville 16, Tenn. 1301 Hannah Ave.
 Lake Charles, La. 422 Seventh St.
 Lansing 8, Mich. 306 Michigan National Tower
 Lexington, Ky. First National Bank Bldg.
 Lincoln 8, Nebr. Sharpe Bldg., 206 S. 13th St.
 Little Rock, Ark. 103 W. Capitol Ave.
 Los Angeles 54, Calif. 212 N. Vignes St.
 Louisville 2, Ky. 455 S. Fourth St.
 Lubbock, Texas. 3302 Avenue "A"
 Macon, Ga. 682 Cherry St.
 Madison 3, Wisc. 16 N. Carroll St.
 Manchester, N. H. 875 Elm St.

Medford, Ore., P.O. Box 1349, 107 E. Main St.
 Memphis 3, Tenn. 8 N. Third St.
 Miami 32, Fla. 25 S.E. Second Ave.
 Midwest City, Okla. Avia. & Def.,

207 Post Off. Bldg.
 Milwaukee 3, Wisc. 940 W. St. Paul Ave.
 Minneapolis 3, Minn. 12 S. Sixth St.
 Mobile 13, Ala. 54 St. Joseph St.
 Nashville 3, Tenn. 234 Third Ave., N.
 Newark 2, N. J. 744 Broad St.
 New Haven 6, Conn. 129 Church St.
 New Orleans 12, La. 837 Gravier St.
 New York 22, N. Y. 570 Lexington Ave.
 New York Avia. & Def., Fed. Bldg.,
 N. Y. International Airport, Jamaica 30, N. Y.

Niagara Falls, N. Y. 253 Second St.
 Norfolk 10, Va. 229 W. Bute St.
 Oakland 12, Calif. 409 Thirteenth St.
 Oklahoma City 2, Okla. 119 N. Robinson St.
 Omaha 2, Nebr. 409 S. Seventeenth St.
 Pasco, Wash. 824 W. Lewis St.
 Peoria 2, Ill. 309 Jefferson Bldg.

Philadelphia 2, Pa. 1405 Locust St.
 Phoenix, Ariz. P.O. Box 4037, 303 Luhrs Tower
 Pittsburgh 22, Pa. The Oliver Bldg., Mellon Sq.
 Portland 7, Ore. 920 S.W. Sixth Ave.
 Providence 3, R. I. Industrial Trust Bldg.
 Raleigh, N. C. Room 401, 16 W. Martin St.
 Reading, Pa. 31 N. Sixth St.
 Richmond 17, Va. 700 E. Franklin St.
 Riverside, Calif. 3570 Ninth St.
 Roanoke 16, Va. 920 S. Jefferson St.

Rochester 4, N. Y. 89 E. Ave.
 Rockford, Ill. 110 S. First St.
 Rutland, Vt. 38 1/2 Center St.
 Sacramento 14, Calif. 626 Forum Bldg.
 Saginaw, Mich. Second National Bank Bldg.
 St. Louis 1, Mo. 818 Olive St.
 Salt Lake City 9, Utah. 200 S. Main St.
 San Antonio 5, Texas. 434 So. Main Ave.
 San Diego 1, Calif. 1240 Seventh Ave.

San Francisco 6, Calif. 235 Montgomery St.
 San Jose 10, Calif. 460 Park Ave.
 Savannah, Ga. 4 E. Bryan St.
 Seattle 4, Wash. 710 Second Ave.
 Seattle 8, Wash. Avia. & Def., 220 Dawson St.
 Shreveport, La. 206 Beck Bldg.
 Sioux City 13, Iowa. 572 Orpheum Electric Bldg.
 South Bend 1, Ind. 112 W. Jefferson Blvd.
 Spokane 4, Wash. S. 162 Post St.

Springfield, Ill. 607 E. Adams St.
 Springfield 3, Mass. 1387 Main St.
 Stockton, Calif. 11 So. San Joaquin St.
 Syracuse 6, N. Y. 3532 James St.
 Tacoma 1, Wash. 1202 Washington Bldg.
 Tampa 6, Fla. 1206 North A St.
 Toledo 4, Ohio. 420 Madison Ave.

Trenton 8, N. J. 214 E. Hanover St.
 Tucson, Ariz. P.O. Box 710, 650 N. Sixth Ave.
 Tulsa 3, Okla. 320 S. Boston Ave.
 Utica 2, N. Y. 258 Genesee St.
 Washington 5, D. C. 777-14th St., N.W.
 Waterloo, Iowa. 206 W. 4th St.
 Wenatchee, Wash. 328 N. Wenatchee Ave.

Wheeling, W. Va. 40 Fourteenth St.
 Wichita 2, Kan. 200 E. First St.
 Williamston, N. C. 115 E. Main St.
 Worcester 5, Mass. 288 Grove St.
 York, Pa. 56 N. Harrison St.
 Youngstown 5, Ohio. 272 E. Indianola Ave.

Hawaii: American Factors, Ltd., P. O. Box 3230, Honolulu 1

Canada: Canadian General Electric Company, Ltd., Toronto

24

GENERAL ELECTRIC COMPANY, PHILADELPHIA, PA.